

Line Utilization Program - 16 Learnings

- 1. A lot of base hits add up to great results.
- 2. The data doesn't do anything unless you <u>drive</u> action.
- 3. Take the time to define our processes & then roll out.
- 4. Strong, active & visible executive leadership makes all the difference in change management.
- 5. Take the time to make sure changes take hold. Soak time is needed.
- 6. Need targets to go "red" 10% of the time to improve.
- 7. Data integrity eliminates arguments.
- 8. Real savings only happen if we sell more....so we must update ERP to make our increase capacity visible to planners.

- 9. It is more valuable to benchmark OEE against yourself.
- 10. Automated data collection doesn't make sense everywhere. In those locations, just use manual data capture.
- 11. Measure downtime at the bottleneck(s). The bottlenecks can move.
- 12. Commit to the 5 whys.
- 13. Must track scheduled downtime too, to get the full picture.
- 14. To sustain results, we must work at it and keep it visible to the organization as a whole.
- 15. Root Cause Analyses Quality is foundational
- 16. Audits are critical and training must be in place to address gaps.